

# Bottle Labelling


915 Ionising Bars



Packaging > bottle labelling > ISSUE 2

## Problem

The build up of static electricity on the label web or on the plastic bottles will result in poor label feeding or incorrect label placement and positioning. These problems can result in the mislabelling of bottles, slower production speeds and a higher defect rate.



## Solution

Model 915 ionising bars positioned as shown above will neutralise static charges on the label web and the plastic bottles. This solution will allow correct labelling and improve process productivity.

Products shown in this document may be covered by one or more patents, patents applied for and/or registered designs and/or trade marks. For further information please refer to our Head Office or visit [www.meech.com](http://www.meech.com).

Meech International

UK: +44 1993 706 700  
Hungary: +36 27 535 075

USA: +1 330 564 2000  
China: +86 21 6119 6725

Belgium: +32 8067 0204

email: [sales@meech.com](mailto:sales@meech.com)  
web: [www.meech.com](http://www.meech.com)

© Meech Static Eliminators Ltd 2010

