

Stenter (Flaker) Machines

915 Ionising Bars




Textiles > general002 > ISSUE 2

Problem

Textiles are delivered directly onto a frame via a swing arm. The following problems can arise:

1. Static causes the product to cling or attract onto the frame sides.
2. Contamination of product due to dust attraction.



Solution

Two Model 915 antistatic bars positioned at the end of the swing arm ensures that the product is fed onto the frame free of static. The Model 915 bars also ensure the product is contaminant-free and the risk of shocks to the operators is removed.

Products shown in this document may be covered by one or more patents, patents applied for and/or registered designs and/or trade marks. For further information please refer to our Head Office or visit www.meech.com.

Meech International

UK: +44 1993 706 700
Hungary: +36 27 535 075

USA: +1 330 564 2000
China: +86 21 6119 6725

Belgium: +32 8067 0204

email: sales@meech.com
web: www.meech.com

© Meech Static Eliminators Ltd 2010

